

January 3, 2023

Ms. Nuria Muniz National Priorities List Coordinator U.S. Environmental Protection Agency 77 West Jackson Boulevard Chicago, Illinois 60604

Subject: Final Preliminary Assessment Report

JCI/Tyco Marinette PFAS Plume Site

EPA Identification Number: WIN 000 521 815

EPA Contract No.: 68HE0519D0005

Task Order-Task Order Line Item No.: F0072-0001DD104

Document Tracking No. 1241a

Dear Ms. Muniz:

The Tetra Tech, Inc. (Tetra Tech) Superfund Technical Assessment and Response Team (START) submits this final preliminary assessment (PA) report regarding the Johnson Controls International (JCI)/Tyco Fire Products LP (Tyco) Marinette per- and polyfluoroalkyl substances (PFAS) Plume site in Marinette, Marinette County, Wisconsin. The references cited in the PA have been uploaded to the EPA Region 5 NPL Site Assessment SharePoint site, folder JCI/Tyco Marinette PFAS plume, subfolder Preliminary Assessment.

Please call me at (518) 817-2873 if you have any questions or comments regarding this submittal.

Sincerely,

Alicia Shultz

Environmental Scientist

Enclosure

cc: Karl Schultz, Tetra Tech Program Manager

Mayra Arroyo, Tetra Tech Document Control Coordinator

TO-TOLIN File

ALACAA SHULTZ

FINAL PRELIMINARY ASSESSMENT REPORT JCI/TYCO MARINETTE PFAS PLUME SITE MARINETTE, MARINETTE COUNTY, WISCONSIN

Prepared for

U.S. Environmental Protection Agency

Superfund Division Region 5 77 West Jackson Boulevard Chicago, IL 60604

Submitted by

Tetra Tech Inc.1 South Wacker Drive, 37th Floor Chicago, IL 60606

EPA Contract No. 68HE0519D0005

Task Order-Task Order Line Item No.: F0072-0001DD104 Document Tracking No. 1241a

January 3, 2023

CONTENTS

Sectio	<u>n</u>		<u>Page</u>
1.0	INTRODUCTION		
2.0	SITE BACKGROUND		
2.1	SITE LOCATION AND DESCRIPTION2		
2.2	OPERATIONAL AND REGULATORY HISTORY3		
2.3	PREVIOUS INVESTIGATIONS		
	2.3.1	Stanton Street Facility	3
	2.3.2	FTC Facility	5
2.4	SOURCE AF	REA AND WASTE CHARACTERISTICS	8
3.0	PATHWAYS		8
3.1	3.1 GROUND WATER MIGRATION PATHWAY		8
	3.1.1	Geology and Hydrogeology - Stanton Street Facility	8
	3.1.2	Geology and Hydrogeology - FTC Facility	9
	3.1.3	Groundwater Targets	10
3.2	SURFACE V	VATER MIGRATION PATHWAY	12
	3.2.1	Target Distance Limit	12
	3.2.2	Targets	14
3.3	SOIL EXPOSURE AND SUBSURFACE INTRUSION AND AIR MIGRATION PATHWAYS15		
4.0	DATA GAPS		16
5.0	SUMMARY AND CONCLUSIONS		
5.0	REFERENCES		

Appendices

A FIGURES

1.0 INTRODUCTION

The U.S. Environmental Protection Agency (EPA), under authority of the Comprehensive Environmental

Response, Compensation, and Liability Act of 1980 (CERCLA) and the Superfund Amendments and

Reauthorization Act of 1986 (SARA), tasked the Tetra Tech, Inc. (Tetra Tech) Superfund Technical

Assessment and Response Team (START) with conducting a preliminary assessment (PA) of the Johnson

Controls International (JCI)/ Tyco Fire Products LP (Tyco) Marinette per- and polyfluoroalkyl substances

(PFAS) Plume site (the site) in Marinette, Marinette County, Wisconsin. The PA was completed under

Contract No. 68HE0519D0005, Task Order-Task Order Line Item No. (TO-TOLIN): F0072-0001DD104.

Purposes of a PA are to review existing information about a site and its environs to assess threats, if any,

posed to public health, welfare, or the environment, and to determine if further investigation under

CERCLA/SARA is warranted. The scope of the PA includes reviewing and gathering information

available from federal, state, and local agencies. By use of these sources of existing information,

evaluation of the site ensues via application of EPA Hazard Ranking System (HRS) criteria to assess the

relative threat associated with actual or potential releases of hazardous substances at the site. EPA has

adopted the HRS to help set priorities for further evaluation and eventual remedial action at hazardous

waste sites. The HRS is the primary method of evaluating a site's eligibility for placement on the

National Priorities List (NPL). The NPL identifies sites where EPA may conduct remedial response

actions. This report summarizes findings of the PA of the site.

Preparation of this PA report proceeded according to guidance from the EPA publications Guidance for

Performing Preliminary Assessments under CERCLA and "Hazard Ranking System Final Rule"

(References [Ref.] 1; 2).

The remainder of this PA report is organized as follows:

• Section 2.0 discusses the site background—its location and a description of it, its operational and regulatory history, previous investigations of the site, and source area and waste characteristics.

• Section 3.0 describes the groundwater migration, surface water migration, soil exposure and

subsurface intrusion, and air migration pathways; and data gaps.

• Section 4.0 summarizes PA activities and provides conclusions.

• Section 5.0 lists sources referenced for development of this PA report.

Figures are in Appendix A.

Final Preliminary Assessment January 2023 Tetra Tech, Inc. JCI/Tyco Marinette PFAS Plume Site

JCI/Tyco Marinette PFAS Plume Site Task Order-Task Order Line Item No.: F0072-0001DD104

2.0 SITE BACKGROUND

This section discusses the site background—its location and a description of it, its operational and regulatory history, previous investigations of the site, and source area and waste characteristics.

2.1 SITE LOCATION AND DESCRIPTION

The site consists of two facilities approximately 2 miles apart and area(s) where a hazardous substance has been deposited, stored, disposed, or placed, or has otherwise come to be located (see Figure 1 in Appendix A) (Ref. 3). The Tyco Stanton Street Facility is at 1 Stanton Street in Marinette, Wisconsin, and in Section 6, Township 30 North, Range 24 East (Ref. 4) (see Figures 1 and 2 Appendix A). Geographic coordinates at the Stanton Street Facility, as measured from the approximate center of the property, are 45.0993 degrees north latitude and 87.6188 degrees west longitude (Ref. 4). The Stanton Street Facility encompasses (1) about 66 acres of land, including the main plant on the west side; (2) the former Salt Vault and an undeveloped area to the east referred to as the Wetlands Area; and (3) an office building and parking lot on the south side. The Stanton Street Facility is bordered north by the Menominee River; east by City of Marinette property; south by Water Street, City of Marinette property, Marinette School District property, and commercial and residential properties; and west by Marinette Marine (see Figure 2 in Appendix A) (Ref. 5, p. 3).

The JCI/Tyco Fire Technology Center (FTC) is at 2700 Industrial Parkway South in Marinette, Wisconsin, in Section 12, Township 20 North, Range 23 East (see Figure 1 in Appendix A) (Ref. 6, p. 1). Geographic coordinates at the FTC, as measured from the approximate center, are 45.0774 degrees north latitude and 87.6439 degrees west longitude (Ref. 7). The FTC encompasses about 380 acres of land, of which approximately 9 acres is occupied by the Outdoor Testing/Training Area (OTA). The remining portion of the FTC is used for manufacture of metal fire suppressant components, warehousing, office or classroom activities, and parking, or is undeveloped. The FTC is bordered north by industrial, commercial and city owned properties and Marinette School District property; south by residential, commercial and industrial properties and county owned property; east by a cemetery and school and city owned and residential properties; and west by residential, industrial and commercial properties (see Figure 3 in Appendix A) (Ref. 6, p. 4).

2.2 OPERATIONAL AND REGULATORY HISTORY

Initial use of the Stanton Street Facility was for lumber mill operations, sawdust disposal, and lumber

storage. In 1915, manufacturing operations began with production of cattle feed, refrigerants, and

specialty chemicals. Between 1957 and 1977, manufacture of an arsenic-based agricultural herbicide

occurred at the facility. A byproduct of this was a salt containing arsenic (as high as 2 percent by weight)

that the facility stockpiled on its premises. Arsenic subsequently entered soil and groundwater at the

facility and sediment in the Menominee River. By 1978, the facility had ceased production of the arsenic-

based herbicide, and since 1983, has produced only fire extinguishers and fire suppression systems.

Current processes at the facility involve blending, packaging, storing, shipping, and handling of PFAS-

containing materials (Ref. 5, p. 3).

The FTC Facility currently consists of the OTA, a hydraulics lab with an outdoor foam testing pad, and

various buildings for fire testing, research, and development and quality testing activities. Believed

present as well is another outdoor testing area previously referred to as the Marine Testing Area;

however, neither Tetra Tech nor its sources have been able to determine the location of this area. The

OTA, constructed in approximately 1961, has been used for testing, demonstrations, and training on a

range of fire suppressants (both dry chemical and foam-containing products). Aqueous film-forming

foams (AFFFs) historically have been used at the OTA as part of research and development, quality and

military specification testing, and firefighting training activities. AFFF has not been sprayed outdoors at

the OTA since November 2017 (Refs. 7, p. 4; 8, p 3).

The OTA and other buildings have undergone various improvements, expansions, and revisions over

time, including additions of concrete floors, oil/water separators, sewer line connections, and wastewater

collection points (Ref. 8, pp. 2, 3, 4).

2.3 PREVIOUS INVESTIGATIONS

Section 2.3.1 recounts previous site investigations and removal actions at the Stanton Street Facility, and

Section 2.3.2 describes previous site investigations at the FTC Facility.

2.3.1 **Stanton Street Facility**

Investigations and remedial actions at the Stanton Street Facility have occurred primarily to address

arsenic impacts in soil and groundwater beginning in 1974, with continuation by Tyco after it acquired

the facility in 1990. Tyco implemented several corrective measures through the Resource Conservation

Final Preliminary Assessment January 2023

ED 014293 00000915-00006

and Recovery Act (RCRA) program, including: (1) construction of a barrier wall consisting of sections of vibrated beam slurry wall and sheet pile around the perimeter of the facility, (2) installation of a groundwater collection and treatment system in response to the arsenic contamination, (3) removal of onsite surficial soil containing total arsenic concentrations greater than 32 milligrams per kilogram (mg/kg) and of surficial soil in three off-site areas with total arsenic concentrations equal or exceeding 16 mg/kg, and (4) dredging of 259,000 cubic yards of sediments from the Menominee River during 2012-2014 to remove sediments with total arsenic concentrations between 50 and 20 mg/kg (Ref. 5, p. 4). Tyco continues to address the arsenic contamination under the RCRA program, and therefore this PA does not evaluate the arsenic contamination. This PA focuses on PFAS contamination identified during investigations at the Stanton Street Facility. Based on presence of PFAS-containing materials in blending operations at the facility, investigations focused on PFAS have revealed presence of it in soil, groundwater, and surface water (Ref. 5, p. ES-1). Available documentation does not identify the source of the release. Results of the investigations are discussed below.

Groundwater sampling for PFAS began in 2018, and PFAS was detected in shallow groundwater. The groundwater data indicate that highest concentrations of PFAS are in shallow groundwater within the facility's hydraulic barrier (Ref. 5, p. 3 and Figure 5). Concentrations outside the hydraulic barrier were generally lower than at wells inside the barrier except at MW003S, where perfluorooctanoic acid (PFOA) was detected at 1,200 D nanograms per liter (ng/L), and perfluorooctanesulfonic acid (PFOS) at 220 ng/L (D = Dilution required for sample analysis). PFOA and PFOS concentrations exceeded the EPA drinking water Lifetime Health Advisory Level (HAL) of 70 ng/L, and the Wisconsin Department of Natural Resources (WDNR) recommended enforcement standard of 20 ng/L for individual or combined values of PFOA and PFOS inside and outside the hydraulic barrier (Refs. 5, pp. 13-15, Table 3, Figure 5; 9, p. 1). Investigations have shown that essentially all overburden groundwater inside the facility's containment wall is captured. Overburden groundwater outside of the wall flows around the barrier to the Menominee River (Ref. 5, p. 17).

A shallow soil sampling event was performed in November 2019. PFOA and PFOS results for eight soil samples collected at the facility in November 2019 were below the WDNR PFOA and PFOS non-industrial (1,260 micrograms per kilogram [μ g/kg]) and industrial (16,400 μ g/kg) direct contact residual contaminant levels for soil. The maximum PFOS concentration detected in soils at the facility was 4.7 μ g/kg and the maximum PFOA concentration detected was 15 μ g/kg (Refs. 5, p. 15, Table 4, Figure 7; 10, p. 1).

ED 014293 00000915-00007

Surface water samples have been collected periodically by WDNR, the City of Marinette, and the City of Menominee in the Menominee River and Bay of Green Bay upgradient and downgradient of the Stanton Street Facility. As of February 12, 2020, PFOA and PFOS concentrations in the surface water samples were below the WDNR proposed surface water quality guidelines. Proposed levels of public health significance are 20 ng/L in waters classified as public water supplies under chapter NR 104, and 95 ng/L for other surface waters. (Refs. 5, pp. ES-2, 164, Figures 4 and 9; 10, pp. 3, 6).

2.3.2 FTC Facility

Tyco has conducted extensive phased investigations to characterize the nature and extent of the PFAS releases from the FTC Facility. Investigations included groundwater, surface water, sediment, stormwater, and soil sampling; bedrock characterization; surface water and groundwater elevation monitoring; surface water velocity measurement; and sewer line inspection and rehabilitation (Ref. 6, pp. ES-1, 13). A summary of the investigations is provided below.

2.3.2.1 Groundwater

In August 2018 and August 2019, 19 monitoring wells were sampled for PFAS using low-flow methods. The investigations delineated the distribution of PFAS in groundwater around the FTC Facility. In 2018, PFOS results ranged from non-detect to 15,000 ng/L. FTC Facility Well FTC-34D, located on the east side of the OTA, exhibited the highest concentration of PFOS. PFOA results ranged from non-detect to 46,000 D ng/L. The highest PFOA result was detected in PZ-1S, located on the northeast corner of the FTC Facility. PFOS results for MW-100-32 and MW-101-16, located outside and downgradient of the Tyco FTC Facility property, were non-detect and 5.4 ng/L, respectively. Results for PFOA in MW-100- 68 and MW-101-72, located downgradient of the FTC Facility, were non-detect and 1,300 ng/L, respectively (Ref. 6, pp. 28, 29, Table 11, Figure 14).

In 2019, the 2018 groundwater monitoring event was duplicated, and the same 19 wells were sampled a second time. Concentrations of PFOA and PFOS generally decreased in 2019 from the concentrations detected in 2018. PFOS results ranged from non-detect to 10,000 ng/L. PFOA results ranged from 1.2 J ng/L to 43,000 EJ ng/L (J = The result is an estimated quantity. The data qualifier E is not defined in the report.) (Ref. 6, p. 29, Table 11, Figure 14).

The horizontal limits of PFOA and PFOS in groundwater above the Wisconsin Department of Health Services (WDHS) recommended enforcement standard of 20 ng/L for PFOA (Ref. 9) were found to extend eastward from a source area at the OTA, moving with groundwater to the northeast and southeast.

Final Preliminary Assessment January 2023 Tetra Tech, Inc. JCI/Tyco Marinette PFAS Plume Site Task Order-Task Order Line Item No.: F0072-0001DD104 The lateral extent includes a portion of the City of Marinette, extending northeast from the FTC Facility toward the Menominee River, and portions of the City of Marinette and Town of Peshtigo extending southeast approximately as far as Rader Road (Ref. 6, pp. 27-29, Tables 9-11, Figure 15).

2.3.2.1 Surface Water

The nature and extent of PFAS in surface water related to the FTC Facility have been defined for Ditches A and B where PFOA and PFOS concentrations were present in surface water above the WDNR proposed surface water quality criteria (see Figure 7 in Appendix A) (Refs. 6, pp. ES-1, ES-2, 31, Tables 13 and 14, Figure 5 and 16 to 23; 10, pp. 3, 6). The proposed WDNR surface water quality guidelines are 20 ng/L in waters classified as public water supplies under chapter NR 104 and 95 ng/L for other surface waters (Ref. 10, pp. 3, 6). Concentrations of PFOS ranged from non-detect to 1,100 D ng/L, and PFOA concentrations ranged from non-detect to 6,000 D ng/L. Ditch segments where PFOA and PFOS concentrations exceeded the guidelines include Ditch A, extending downstream from the FTC Facility to a location upstream of a sample point where the ditch crosses Rader Road and Ditch B, from approximately where the ditch crosses Pierce Avenue downstream to Bay of Green Bay (Ref. 7, pp. 30-31, Table 13, Figures 16-18). The ditches flow through residential neighborhoods (Ref. 6, Figures 21-23).

2.3.2.2 Sediment

In 2018, twenty-seven sediment samples were collected from 18 locations (SD-1 to SD-18) within drainage ditches receiving surface water runoff from the facility and analyzed for PFAS. Concentrations of PFOS ranged from non-detect to 100 μg/kg, and PFOA concentrations ranged from non-detect to 550 μg/kg. The highest concentrations of PFOS and PFOA were detected in on-site sediment samples collected from Ditch A (Ref. 6, Figure 24). PFOS and PFOA concentrations decreased in sediment samples collected farther downstream in Ditch A. Overall, the results show that PFAS are present in sediment in Ditch A within the property boundaries, and at rapidly decreasing concentrations downstream (i.e., 2 μg/kg for PFOA and less than 0.9 μg/kg for PFOS at the most downstream sample point near Rader Road) (Ref. 6, p. 32 and Figures 19 through 24).

Low concentrations of PFOS and PFOA were observed in the Ditch B sediments and ranged from nondetect to 4.4 μ g/kg for PFOS and non-detect to 4.0 μ g/kg for PFOA (Ref. 6, p. 32).

2.3.2.3 Stormwater

Stormwater runoff samples were collected from the FTC Facility to evaluate stormwater runoff from the OTA. The two stormwater runoff samples, SW-01 and SW-04, collected in March 2018 near the OTA had PFOS detections of 1,200 ng/L and 41 ng/L, respectively, and PFOA detections of 860 ng/L and

710 ng/L, respectively. Concentrations in stormwater runoff samples collected from four on-site locations

(SW-FTC-01 through SW-FTC-04) during three seasonal precipitation events in April, May, and October

2019 ranged from 11 ng/L to 5,100 ng/L for PFOS and 50 ng/L to 6,400 ng/L for PFOA. Concentrations

in stormwater runoff samples collected from the four outfall sampling locations (OS-01 through OS-04)

in November 2019 ranged from non-detect to 9.8 ng/L for PFOS and non-detect to 130 ng/L for PFOA

(Ref. 6, p. 32, Table 15, Figures 4 and 24).

2.3.2.4 Soil

From 2013 to 2019 during multiple phases of work a total of 66 soil samples were collected within and

near the OTA, no concentrations of PFOA and PFOS were detected in soil that exceeded the WDNR

calculated direct contact criteria for non-industrial (1,260 µg/kg) and industrial soils (16,400 µg/kg)

(Refs. 6, pp. 33-34, Table 17, Figure 25; 27, p. 1). None of the concentrations exceed the EPA Regional

Screening Level (RSL) for residential and industrial soil (Refs. 12; 13). Background concentrations for

PFAS, PFOA, and PFOS were not established during the investigation.

In October 2013 and April 2014, eight soil samples (FTC-59, FTC-60, FTC-62, FTC-71, FTC-72, FTC-

77, FTC-82, and FTC-83) were collected from the OTA and analyzed for PFAS compounds. PFOS

concentrations within the 2013 to 2014 soil samples ranged from non-detect to 580 µg/kg, and PFOA

concentrations ranged from non-detect to 122 µg/kg (Ref. 6, pp. 22, 33).

In August and September 2016, 16 soil samples were collected from boring locations SS-97 to SS-110

and analyzed for PFAS compounds. PFOS concentrations within the soil samples ranged from 0.22 J

μg/kg to 380 μg/kg, and PFOA concentrations ranged from 0.73 μg/kg to 1,300 μg/kg (Ref. 6, p. 33).

A total of 32 soil samples were collected from 17 on-site direct push technology borings (SS-113 to SS-

129) in June and July 2018 and analyzed for PFAS compounds. The PFOS concentrations within the soil

samples ranged from non-detect to 450 D µg/kg, and the PFOA concentrations ranged from non-detect to

440 D μg/kg (Ref. 6, p. 33).

Ten soil samples were collected from locations SS-130 to SS-139 in July 2019 and analyzed for PFAS.

The PFOS concentrations within the 2019 soil samples ranged from non-detect to 800 D µg/kg, and the

PFOA concentrations ranged from 0.56 μg/kg to 1,100 μg/kg (Ref. 6, p. 33).

Leach testing was also completed on eight soil samples in 2019 using groundwater from MW-100-32 as

Final Preliminary Assessment

Tetra Tech, Inc. JCI/Tyco Marinetie PFAS Plume Site

January 2023

Task Order-Task Order Line Item No.: F0072-0001DD104

,

an eluant (liquid solvent). PFOS concentrations within the eluant ranged from 18 ng/L to 6,900 D ng/L, and concentrations of PFOA ranged from 10 ng/L to 2,900 ng/L (Ref. 6, pp. 33, Table 18).

2.4 SOURCE AREA AND WASTE CHARACTERISTICS

The sources identified at the Site are an area of observed contaminated soil at the OTA on the FTC Facility, two intermittent drainage ditches draining the FTC Facility, and the area of soil contamination at the Stanton Street Facility. Soil sampling investigations identified approximately 23 acres (1,001,880 square feet) of PFAS-contaminated soil at the OTA (Source No. 1) (see Figure 6 in Appendix A). The area of soil contamination in the drainage ditches (Source No. 2) associated with the FTC is assumed to be greater than zero (see Figure 7 in Appendix A). Soil sampling investigations identified approximately 13 acres (566,280 square feet) of PFAS-contaminated soil at the Stanton Street Facility (Source No. 3) (see Figure 8 in Appendix A).

3.0 PATHWAYS

This section discusses the ground water migration, surface water migration, soil exposure and subsurface intrusion, and air migration pathways. Additionally, this section discusses the targets associated with each pathway and draws pathway-specific conclusions.

3.1 GROUNDWATER MIGRATION PATHWAY

This section discusses the geology and hydrogeology of the Stanton Street and FTC facilities and the targets associated with this pathway, and previous residential sampling investigations.

3.1.1 Geology and Hydrogeology - Stanton Street Facility

The Stanton Street Facility overlies approximately 35 to 45 feet of unconsolidated materials, comprising fill, alluvium or lakebed sediments, and till. The upper fill layer consists of sand and gravel with cinders, woodchips, brick, and glass. Alluvial deposits consisting of fine- to coarse-grained sand and gravel with varying amounts of silt underlie the fill layer. Underlying this alluvium is a layer of silty sand to sandy silt lacustrine deposits. This predominantly silt lacustrine layer transitions to a compacted glacial till deposit consisting of denser sandy silt and clay. Dolomitic bedrock is generally encountered beneath the unconsolidated deposits at a depth of approximately 40 feet below ground surface (bgs). In borings completed at the Stanton Facility, the bedrock surface is overlain by 5 feet or more of dense till, which provides hydraulic confinement between the bedrock and shallow groundwater (Ref. 5, p. 3).

Final Preliminary Assessment January 2023 Tetra Tech, Inc. JCI/Tyco Marinette PFAS Plume Site Task Order-Task Order Line Item No.: F0072-0001DD104 The water table in the vicinity of the Stanton Street Facility is typically less than 5 feet bgs, generally occurring within the shallow fill materials and flows to the north. Groundwater in the fill and alluvial deposits is hydraulically connected, while the glacial till acts as an aquitard. The bedrock underlying the till appears to be confined, and bedrock groundwater may be predominantly controlled by fracture flow. Some boreholes completed in uppermost bedrock (e.g., more than 10 to 15 feet below the rock surface) encountered fractured and weathered rock with moderate permeability. Other locations attempted in shallow rock encountered no open fractures and could not be completed as wells (Ref. 5, p. 4).

3.1.2 Geology and Hydrogeology - FTC Facility

The FTC Facility is located in a low-relief plane, approximately one mile west of Bay of Green Bay (see Figure 1 in Appendix A). The surficial geology in the City of Marinette and Town of Peshtigo areas was mapped by the United States Geological Survey as glacial lake deposits, consisting mainly of clay, silt, and sand, overlying Ordovician dolomite bedrock (Ref. 14, Plate 1). Observed overburden deposits consist of a sequence of sands and finer-grained deposits that thicken above a sloping bedrock surface from less than 15 feet north and west of the FTC to greater than 100 feet along the Bay of Green Bay shoreline. The glacial deposits vary in composition across the facility. In general, the bulk of the observed materials are sands, consistent with a glacial lake shore environment of beach facies and dunes. These deposits are interbedded with lower-permeability silts and clays, reflecting lower-energy glacial lake sediments. Dense glacial till is typically observed directly above the rock surface (Ref. 6 pp. 4, 5).

Beneath the FTC, sands extend to approximately 35 feet, coarsening with depth, overlying 10 feet or more of till above the bedrock surface. To the east and south, as the overburden thickens, the sands separate into distinct shallow and deep units separated by an aquitard consisting of silts and clay. The silts and clays behave as an aquitard that thickens toward Bay of Green Bay (Ref. 6, pp. 4, 5, Appendix B).

The water table throughout the facility is shallow, generally less than 5 feet bgs. Groundwater beneath the FTC is interpreted to flow generally eastward, with flow paths radiating along an arc from southeast to northeast, discharging to Bay of Green Bay and the Menominee River. Groundwater in the shallow sand unit discharges locally into the network of ditches flowing through the facility and surrounding area. Groundwater in the deeper sand unit may flow beneath ditches on flow paths that trend more directly toward Bay of Green Bay or the Menominee River (Ref. 6, pp. 4, 5).

Final Preliminary Assessment January 2023

JCI/Tyco Marinette PFAS Plume Site

Task Order-Task Order Line Item No.: F0072-0001DD104

3.1.3 Groundwater Targets

The HRS evaluates threats to drinking water wells (groundwater targets) within a 4-mile radius target distance limit (TDL) category measured from the edges of sources. Figure 9 in Appendix A, 4-mile TDL limit map, shows the locations of residential drinking water wells within each TDL category. The radius is drawn from the edges of Source Nos. 1 and 3. Source No. 2, drainage ditches, is not included on the figure. Including Source 2 on Figure 9 makes the figure illegible because the ditches cover long distances and weave. The U.S. Census Bureau persons per household value for Marinette County for 2008 to 2012 is 2.09. Specifically, the number of wells and population values within a 4-mile radius are distributed as follows: >0 to 0.25 mile, 0 wells (0 people); >0.25 to 0.50 mile, 142 wells (296.78 people); >0.50 to 1.0 mile, 38 wells (79.42 people); >1.0 to 2.0 miles, 205 wells (428.45 people); >2.0 to 3.0 miles, 12 wells (25.08 people); >3.0 to 4.0 miles, 0 wells (0 people) (Ref. 15). Therefore, about 829.73 persons (397 wells × 2.09 persons per household) are served by drinking water wells within a 4-mile radius of Source Nos. 1 and 3. The sources have the potential to contaminate these drinking water wells. No public drinking water supply wells are located within the 4-mile radius of the sources.

The HRS also evaluates actual contamination of drinking water wells within the 4-mile TDL. Actual contamination of drinking water wells has been documented through long-term potable well sampling programs. Arcadis, on behalf of Tyco, conducts long-term potable well sampling for the FTC Facility in Marinette, Wisconsin under two separate programs:

- 1. A private well sampling area (PWSA) program as defined by Tyco.
- 2. A Point of Entry Treatment (POET) Monitoring Program (Ref. 16, p. 3).

In addition to the two potable well sampling programs, an Expanded Site Investigation Area sampling of potable wells was conducted from October 23, 2020 through July 12, 2021. A summary of the two potable well sampling programs and the Expanded Site Investigation Area findings are described below.

3.1.3.1 Private Well Sampling Program

A potable well sampling program was initiated in December 2017 for the FTC Facility and continued quarterly for ten events through December 2020 for private drinking water wells within the PWSA. The investigation that was conducted from December 2017 to December 2020 identified approximately forty-one residential wells located in the Town of Peshtigo have concentrations of perfluorohexanesulfonic acid (PFHxS), perfluorononanoic acid (PFNA), perfluorooctanesulfonic acid (PFOS) and perfluorooctanoic acid (PFOA) exceeding the EPA RSL for a cancer target risk (TR) of 1E-06 for oral exposures and a non-carcinogenic target hazard quotient (HQ) of 0.1. Approximately eleven residential wells located in the

Town of Peshtigo have concentrations of PFHxS, PFNA, PFOS and PFOA exceeding the tapwater RSL for a cancer TR of 1E-06 for oral exposures and a non-carcinogenic target HQ of 1 and the HRS benchmarks for drinking water, meeting the HRS criteria for Level I concentrations (Refs. 12, 13; 16; 17).

Quarterly sampling within the PWSA for the FTC Facility was suspended for the spring and summer 2020 events due to COVID-19 but resumed for the fall 2020 event. The summer 2021 quarterly event extends through September 30, 2021. During these events, Arcadis sampled a total of 173 potable wells located generally to the southeast of the FTC Facility where residents rely on private wells for drinking water. The number of wells sampled during each quarter varies based on concentrations detected and access. A summary of the results:

- Potable wells sampled through June 2021: 173
- Potable wells with results above the WDHS enforcement standard of 20 ng/L: 37
- Potable wells with results less than the laboratory reporting limit (RL) and greater than WDHS enforcement standard: 47
- Potable wells with results below the RL (non-detect): 89 (Ref. 16, p. 3).

Bottled water is offered by Tyco to users of the private wells that are within the PWSA regardless of sampling participation or results. The only criteria for being eligible for bottled water within the PWSA is that the tenant has a private drinking water well plumbed to the building that is a primary source of drinking water. Bottled water is managed per the Comprehensive Alternative Water Management Plan submitted to WDNR in March 2020 (Ref. 16, p. 3).

3.1.3.2 POET System Monitoring Program

The POET System Monitoring Program is a separate residential well sampling program specific to wells that have a POET system installed and maintained by Tyco. The POET System Monitoring Program was initiated in February 2018 for potable wells with results above the EPA HAL of 70 ng/L for lifetime exposure to combined PFOS and PFOA concentrations. The program was expanded in July 2018 to include potable wells with initial results and confirmed results above the RL. Private drinking water wells with POET systems are part of the POET Monitoring Program, managed independent of wells without POET systems, and are not subjected to the same sampling criteria as wells within the Private Well Sampling Program. The criteria are not identified in the *Revised Long-Term Potable Well Sampling Plan* documenting the two sampling programs (Ref. 16). Forty-seven POET systems have been installed to date to treat groundwater used as drinking water under this program. Arcadis has collected POET system samples on a regular basis to confirm the effectiveness of PFAS removal and system operations (Ref. 16, p. 3).

Final Preliminary Assessment January 2023 Tetra Tech, Inc.
JCI/Tyco Marinette PFAS Phone Site
Task Order-Task Order Line Item No.: F0072-0001DD104

Analytical results from the private wells in the POET System Monitoring Program prior to the installation of treatment systems indicated the following:

- Potable wells sampled: 47
- Potable wells with results above the WDHS recommended enforcement standard: 23
- Potable wells with results less than the RL and above WDHS enforcement standard: 18
- Potable wells with results below the RL (non-detect): 4 (Ref. 16 Table 2).

3.1.3.3 Expanded Site Inspection Area

An Expanded Site Inspection Area potable well sampling was conducted for the WDNR, Bureau of Remediation and Redevelopment. The analytical data report for the investigation provided analytical results for 418 private wells that were sampled from October 28, 2020 through July 12, 2021. The analytical results identified 32 private wells with PFOS and PFOA concentrations above at least one of the available EPA health-based standards (EPA HAL or EPA RSLs) and HRS benchmarks for drinking water (Refs. 12; 13; 17; 28). The only documentation for the investigation reviewed includes the analytical results.

3.2 SURFACE WATER MIGRATION PATHWAY

Available data indicates that a release of PFAS to drainage ditches, intermittent streams, the Menominee River, and wetlands has occurred from Source Nos. 1 through 3. The surface water migration pathway from Source Nos. 1, 2, and 3 also includes the Little River and the Bay of Green Bay. Surface water runoff from the FTC Facility flows through drainage ditches including Source Nos. 1 and 2 to the Bay of Green Bay or to the Little River and then the Bay of Green Bay, and Source No. 3 drains to the adjacent Menominee River and then to the Bay of Green Bay. Contaminated sediments in the Menominee River attributed to releases from the Stanton Street Facility have been remediated, dredged, and removed; however, the source of the contamination in the Menominee River (Source No. 3) has not been remediated. This section discusses the surface water migration pathway and targets associated with this pathway.

3.2.1 Target Distance Limit

The HRS evaluates surface water targets located along the 15-mile downstream TDL. The TDL is measured from the probably point of entry (PPE) into surface water from each source downstream for 15 miles. The PPE is the point at which the overland segment of a hazardous substance migration path from each source intersects with surface water (Ref. 2). The PPEs for the sources are described below.

Final Preliminary Assessment Tetra Tech, Inc.

January 2023 12 JCI/Tyco Marinette PFAS Plume Site

Task Order-Task Order Line Item No.: F0072-0001DD104

Source No. 1

Surface water runoff from Source No. 1 (OTA) flows directly into Ditch A, which receives runoff from

the FTC (see Figure 5 in Appendix A) (Ref. 6, pp. 4, 19). Ditch A is an intermittent drainage ditch that

flows south from the FTC over 1.5 miles through a series of connecting ditches and streams through the

Town of Peshtigo to Little River. The point at which Ditch A enters Little River is the PPE to surface

water and is shown as PPE-1 in Figure 10 in Appendix A. Little River flows from the PPE approximately

1.17 mile to Bay of Green Bay and the 15-mile downstream TDL is completed in Bay of Green Bay

(Ref. 6, p. 4). For bays, the direction of surface water flow is not considered. The TDL is drawn as an

arc with a radius completing the 15-mile TDL as shown in Figure 10 in Appendix A.

Source No. 2

Source No. 2 includes contaminated sediments within drainage ditches A and B that flow to Bay of Green

Bay (Ref. 6, p. 4). The source of contamination to the ditches is runoff from Source No. 1. Ditch A

flows north to south through the FTC, passing west of the OTA. Ditch A flows south from the FTC

through a series of connecting ditches and streams through the Town of Peshtigo to Bay of Green Bay.

Ditch B flows north of FTC, to the east and then to the south and finally to Bay of Green Bay. It is

assumed that the overland flow route for the two ditches is intermittent water and does not include any

perennial surface water until Ditch A discharges to Little River and Ditch B discharges into Bay of Green

Bay. The most upstream PPE for the two drainage ditches is shown on Figure 10. The PPE for Source

No. 2 overlaps the PPE for Source No. 1, PPE-1.

Source No. 3

Source No. 3 (contaminated soil at Stanton Street) drains to the adjacent Menominee River (PPE-2). The

Menominee River continues 1.34 miles to the Bay of Green Bay (Ref. 5, p. 6). The PPE for Source No. 3

is shown as PPE-2 on Figure 11.

The TDL, 15 miles downstream from the PPEs, is completed in Bay of Green Bay for all sources.

According to the HRS, if hazardous substances from different sources enter the same water body at

different points, the target distance is the combined overlapping arcs for two or more PPEs into a lake,

13

such as Bay of Green Bay. The arcs and the PPEs are shown in Figures 10 and 11 in Appendix A.

Targets within the 15-mile TDL are discussed in the sections below.

Final Preliminary Assessment January 2023 Tetra Tech, Inc. ICI/Tyco Marinetie PFAS Plume Site

Task Order-Task Order Line Item No.: F0072-0001DD104

ED 014293 00000915-00016

3.2.2 **Targets**

Targets associated with surface water migration pathway include drinking water intakes, human food

chain, and environmental.

3.2.2.1 Drinking Water

The Marinette Municipal Water System has two drinking water intakes located within the 15-mile target

distance limit serving 10,910 people. This water is not mixed with any other water supplies before

distribution (Ref. 18). PFOA and PFOS have been detected in samples of the raw water drinking water

intake (Ref. 19, p. 2). The concentrations are below the PFOS and PFOA tapwater RSLs of 4 and 6 ng/L,

respectively, using a TR of 1E-06 and HQ of 0.1 as well HRS health-based benchmarks identified in

Table 3-10 of the HRS Rule (Refs. 12; 19, pp. 1, 2).

3.2.2.2 Human Food Chain

The Bay of Green Bay is used as a fishery. The WDNR and WDHS issued a PFAS-based consumption

advisory for the Bay of Green Bay and its tributaries, including the Menominee River (Ref. 20). Tyco has

scheduled investigations of releases of PFAS to Bay of Green Bay (Ref. 21, p. 5).

3.2.2.3 Environmental Threat

Environmental targets identified within the surface water migration pathway of Source Nos. 1 and 2

include 1.40 miles of wetland frontage (Refs. 22; 23, Figure 1). PFOS sediment contamination has been

detected in this wetland (Ref. 6, Figures 12 and 16). Over 20 miles of additional wetland frontage is

associated with the surface water migration pathway from Source Nos. 1 through 3 and are subject to

potential contamination (Ref. 22).

Federal endangered and threatened species associated with the 15-mile TDL include the endangered Gray

Wolf (Canis lupus) and Hine's Emerald Dragonfly (Somatochlora hineana) and threatened Canada Lynx

(Lynx canadensis), Northern Long-eared Bat (Myotis septentrionalis), Red Knot (Calidris canutus rufa),

and Dwarf Lake Iris (Iris lacustris) (Ref. 24).

Seagull Bar, a state designated Natural Area, is within the 15-mile TDL. Seagull Bar is a sand spit and

14

marsh on the margin of Bay of Green Bay off the City of Marinette owned by the WDNR (Ref. 25).

Final Preliminary Assessment January 2023

JCI/Tyco Marinette PFAS Plume Site

Task Order-Task Order Line Item No.: F0072-0001DD104

ED 014293 00000915-00017

3.3 SOIL EXPOSURE AND SUBSURFACE INTRUSION AND AIR MIGRATION PATHWAYS

The Stanton Street Facility is an active manufacturing facility in the northeastern portion of the City of

Marinette, adjacent to the Menominee River. The facility is bordered by the Menominee River to the

north; City of Marinette property to the east; Water Street, City of Marinette property, Marinette School

District property, and commercial and residential properties to the south; and Marinette Marine to the

west (see Figure 2 in Appendix A) (Ref. 5, p. 3).

The FTC is bordered north by industrial, commercial and city owned properties and Marinette School

District property; south by residential, commercial and industrial properties and county owned property;

east by a cemetery and school and city owned and residential properties; and west by residential,

industrial and commercial properties (see Figure 3 in Appendix A) (Ref. 6, p. 4).

The topography of both facilities and the site consists of flat terrain (see Figure 1 in Appendix A). Access

to the facilities is secured by a fence surrounding the facilities (Refs. 5, p. 4; 26, p. 3; 27, p. 1).

The nearest residents to Source No. 1 are 0.35 feet to the southeast. Marinette High School is located 0.5

mile to the northeast (See Figures 2 and 3 in Appendix A). The drainage ditches comprising Source No. 2

run along commercial and residential areas and in cases are within 200 feet of residential property (See

Figure 7 in Appendix A). The nearest resident to Source No. 3 is 0.20 mile to the southeast (see Figure 8

in Appendix A). Based on the U.S. Bureau of the Census 2010 population data, the residential population

within a 4-mile radius is distributed as follows: >0 to 0.25 mile, 300 persons; >0.25 to 0.50 mile, 1,909

persons; >0.50 to 1.0 mile, 8,450 persons; >1.0 to 2.0 miles, 7,496 persons; >2.0 to 3.0 miles, 2,921

persons; >3.0 to 4.0 miles, 1,681 persons.

The federally designated endangered and threatened species identified in the area of the facilities include

the endangered Gray Wolf (Canis lupus) and Hine's Emerald Dragonfly (Somatochlora hineana) and

threatened Canada Lynx (Lynx canadensis), Northern Long-eared Bat (Myotis septentrionalis), Red Knot

(Calidris canutus rufa), and Dwarf Lake Iris (Iris lacustris) (Ref. 24). The source areas do not appear to

provide adequate habitat for these species due to the high level of human activity and maintenance

activities such as mowing lawns. However, a verification of the absence or presence of these species

Final Preliminary Assessment

Tetra Tech, Inc. ICI/Tyco Marinette PFAS Plume Site

January 2023

Task Order-Task Order Line Item No.: F0072-0001DD104

15

would need to be confirmed by a field investigation. More than 500 acres of HRS eligible wetlands are located within 4 radial miles of the sources (Refs. 22; 23).

No volatile organic compounds have been identified in the sources. Therefore, the sources do not pose a subsurface intrusion threat to occupants of structures. No releases to air from the sources are suspected. However, no air sampling investigations have been conducted at the facilities.

4.0 DATA GAPS

During the PA, the following data gaps were identified.

- Documentation regarding hazardous waste quantity is not available. This may include the amount of PFAS used in the OTA and the quantity of wastewater discharged to the sanitary sewer from the FTC, as well as analytical results of the sanitary sewer discharge. Hazardous waste quantity information was not identified in the FTC and Stanton Street Facility documentation.
- In some cases, the analytical data is older than 5 years. The residential wells, monitoring wells, surface water, sediment, and source samples may need to be re-collected.
- The actual population associated with each residential well is not available.
- Documentation that the residential wells are either closed due to contamination or are still used for drinking water is not available.
- The analytical data for the City of Marinette drinking water intake reviewed as part of this PA was dated December 4, 2020, from the Sanitary Survey Report for the Water Supply Serving the City of Marinette. Public water supplies are typically sampled on a quarterly basis; therefore, more recent data is likely available.
- The PPE from Source No. 2 to Little River needs to be verified. The location of the PPE was estimated based on figures in Reference No. 6.
- The overland flow migration pathway from Source No. 2 needs to verified. The migration pathway was estimated from figures in Reference No. 6.

5.0 SUMMARY AND CONCLUSIONS

The JCI/Tyco Marinette PFAS Plume site consists of two facilities located approximately two miles apart: Stanton Street and FTC Facility. Both facilities have PFAS areas of soil contamination, Source Nos. 1 through 3, that have released to groundwater. The PFAS groundwater contamination at the Stanton Street Facility has been contained by pumping and a containment wall. A PFAS groundwater plume from the FTC Facility extends to residential wells in Marinette. Two residential well sampling programs have been implemented by Tyco detecting PFAS contamination in approximately 41 drinking water wells. The residential wells are sampled on a scheduled basis and the concentrations of PFAS in the wells change during different sampling events. The concentrations detected in the 41 wells have been above one or more of health-based standards such as the EPA HAL of 70 ppt or 70 ng/L; EPA tapwater RSLs for several PFAS; WDHS enforceable standard of 20 ng/L for PFOA and PFOS; and HRS health-based benchmarks.

Surface water runoff from both facilities drain to the Bay of Green Bay. The Stanton Street Facility drains to the Menominee River then to the Bay of Green Bay. The Marinette Municipal Water System has two drinking water intakes located in the Bay of Green Bay that serve 10,910 people. PFOA and PFOS have been detected in samples of the raw water drinking water intake. The concentrations are below the PFOS and PFOA tapwater RSLs of 4 and 6 ng/L, respectively, using a TR of 1E-06 and HQ of 0.1 and HRS health-based benchmarks. The Bay of Green Bay is also used as a fishery and PFAS have been detected in fish tissue samples. WDNR and WDHS issued a PFAS-based consumption advisory for the Bay of Green Bay and its tributaries, including the Menominee River. Numerous federally threatened and endangered may be associated with Bay of Green Bay.

There is the potential for exposure to contaminated soil associated with the drainage ditches, Source No. 2. Access to soil contamination on the facilities is restricted. Subsurface intrusion from Site contaminants is not likely due to the nature of the contaminants, not volatile. There have not been any investigations documenting releases to the air migration pathway.

5.0 REFERENCES

- 1. U.S. Environmental Protection Agency (EPA), Office of Emergency and Remedial Response. Guidance for Performing Preliminary Assessments Under CERCLA. EPA/540/G-91/013. September 1991.
- 2. U.S. Environmental Protection Agency (EPA). Hazard Ranking System, Title 40 Code of Federal Regulations (CFR) Part 300, Appendix A (55 Federal Register [FR] 51583, Dec. 14, 1990, as amended at 82 FR 2779, Jan. 9, 2017; 83 FR 38037, Aug. 3, 2018), as published in CFR on July 1, 2019, with two attachments. Attachment A: FR Vol. 55, No. 241. December 14, 1990. Hazard Ranking System Preamble. Attachment B: FR Vol. 82, No. 5, January 9, 2017. Addition of a Subsurface Intrusion Component to the Hazard Ranking System Preamble. Available at https://semspub.epa.gov/src/document/HQ/100002489.
- 3. Marinette County Ascent Land Records Suite. 2022. Property Search. Search Results for Parcel Identification No. 251-04271.000. Accessed on-line at: Real Estate Tax Parcel (marinettecountywi.gov).
- 4. Google Earth. 2022. Location and Geographic Coordinates of JCI site.
- 5. Arcadis U.S., Inc (Arcadis). 2020. Interim Site Investigation Report Tyco Stanton Street Facility. June.
- 6. Arcadis. 2020. Interim Site Investigation Report Tyco Fire Technology Center. May.
- 7. Google Earth. 2022. Location and Geographic Coordinates of Tyco site.
- 8. Tyco Fire Products LP (Tyco). 2018. Response to WDNR Letter dated January 16, 2018. March 12.
- 9. Wisconsin Department of Health Services. 2022. Groundwater Standard Recommendations (Cycle 11). November 6.
- Wisconsin Department of Natural Resources (WDNR). 2021. Order of the State of Wisconsin Natural Resources Board Amending and Creating Rules. 28 Pages.
 https://dnr.wisconsin.gov/sites/default/files/topic/Rules/WY2319DraftRule2.pdf
- 11. WDNR. 2022. PFAS Investigation and Cleanup.
- 12. EPA. 2022. Regional Screening Level (RSL) Summary Table (TR=1E-06, HQ=0.1). May.
- 13. EPA. 2022. Regional Screening Level (RSL) Summary Table (TR=1E-06, HQ=1). May.
- 14. Oakes, E.L., and L.J. Hamilton. 1973. Water resources of Wisconsin: Menominee-Oconto-Peshtigo River basin (No. 470). U.S. Geological Survey Open.

- 15. United States Census Bureau. 2022. QuickFacts Marinette County, Wisconsin.
- 16. Arcadis. 2021. Revised Long-Term Potable Well Sampling Plan. Tyco Fire Technology Center. October 1.
- 17. Wood Environment and Infrastructure Solutions, Inc. 2021. Potable Well Sampling PFAS Analytical Results. Expanded Site Investigation Area, Marinette County, Wisconsin. Data through 7/12/2021.
- 18. WDNR. 2022. Electronic Mail from Burton Kyle, Field Operations Manager, Bureau of Drinking and Groundwater, Wisconsin DNR. To Nuria Muniz. May 19.
- 19. Marinette Water Utility. 2022. PFOA and FPOS Investigation. July 2022, Update.
- 20. WDNR. New PFAS Fish Consumption Advisory Issued for Bay of Green Bay and Associated Tributaries. January 18, 2022.
- 21. Arcadis. 2020. Fish Tissue and Surface Water Sampling Work Plan. Tyco Fire Technology Center, Marinette, Wisconsin. November.
- 22. Tetra Tech. 2022. Project Note Regarding Wetlands using National Wetlands Inventory (NWI). June 1. Access online at: https://fwsprimary.wim.usgs.gov/wetlands/apps/wetlands-mapper/ and NEPAssist https://www.epa.gov/nepa/nepassist.
- 23. Arcadis. 2019. Wetland and Waterbody Delineation Report. Fire Technology Center, Marinette, Wisconsin. October 10.
- 24. USFWS. 2022. Information for Planning and Consultation (IPaC). Accessed online at: https://ipac.ecosphere.fws.gov/
- 25. WDNR. 2022. Seagull Bar (No. 37). March 31.
- 26. Arcadis. 2018. Site Investigation Report. Tyco Fire Technology Center PFCS, Marinette, Wisconsin. September.
- 27. Arcadis. 2018. Revised Site Investigation Work Plan. Tyco Fire Technology Center Marinette, Wisconsin. April.
- 28. EPA. 2022. Superfund Chemical Data Matrix (SCDM) Query. Query Accessed: 10/24/2022. July.

APPENDIX A

FIGURES

(Eleven Pages)

FIGURE 1	FACILITY LOCATION
FIGURE 2	STANTON STREET FACILITY – VICINITY MAP
FIGURE 3	FIRE TECHNOLOGY CENTER FACILITY - VICINITY MAP
FIGURE 4	STANTON STREET FACILITY – LAYOUT MAP
FIGURE 5	FIRE TECHNOLOGY CENTER FACILITY – LAYOUT MAP
FIGURE 6	SOURCE NO. 1 LOCATION MAP
FIGURE 7	SOURCE NO. 2 LOCATION MAP
FIGURE 8	SOURCE NO. 3 LOCATION MAP
FIGURE 9	4-MILE TARGET DISTANCE LIMIT MAP
FIGURE 10	15-MILE DOWNSTREAM TARGET DISTANCE LIMIT MAP – PPE-1
FIGURE 11	15-MILE DOWNSTREAM TARGET DISTANCE LIMIT MAP – PPE-2

Final Preliminary Assessment

January 2023

JCI/Tyco Marinette PFAS Plume Site
Task Order-Task Order Line Item No.: F0072-0001DD104





















